



## POPCORN

### Popping instructions

1. Turn all switches "**ON**"
2. For first batch only, let kettle heat for 4 minutes.
3. Load the entire contents of the pre-measured popcorn packs.
4. Dump when popping is about 99% completed.
5. Repeat steps 3 and 4, for best results always pop 3-5 batches.
6. (On final batch only) Turn heat switch "**OFF**" when corn raises the lid.
7. Dump kettle when popping is about 99% completed.
8. Turn "**OFF**" kettle motor switch
9. Confirm kettle heat switch is "**OFF**"

### **Caution**

Never touch the kettle. Serious burns may occur.

### **Warning**

Leaving the kettle heat switch on when not popping will cause smoke, burned popcorn, bad odor and will damage the unit.

Call us if you have any questions

**845.226.2447**